


DIGITAL IN/OUTDOOR THERMO-HYGROMETER

OPERATING INSTRUCTIONS



SPECIFICATIONS

1. Indoor Temperature (Internal sensor) Range: -10 C ~ 50 C (14 F ~ 122 F)
2. Outdoor Temperature (External sensor) Range: -50 C ~ 70 C (-58 F ~ 158 F)
3. Outdoor Humidity (External sensor) Range: 10 to 95% RH
4. Sampling Time: 10 seconds
5. Accuracy: $\pm 1^{\circ}\text{C}$; $\pm 5\% \text{RH}$
6. Power: 1.5V AAA * 1pc

FUNCTIONS

1. Display indoor and outdoor two temperature, outdoor humidity.
Use external sensor test outdoor temperature and outdoor humidity.
2. Indoor temperature measured by main body internal sensor.
3. Record maximum and minimum temperature and humidity automatically.
4. Celsius and Fahrenheit switch.
5. The Sucker, for fix the long external sensor wire to some where.
6. Magnet and clip on the back, Stand desk, difference installment way.

BUTTONS

- 【MAX/MIN】 Press to display temperature and humidity maximum and minimum
- 【IN/OUT】 Press to display indoor or outdoor temperature
- 【C/F】 Switch temperature unit between Celsius and Fahrenheit

ATTENTION

1. The thermometer does not have any special shock-proof design, try to avoid dropping.
2. External Temperature Sensor, waterproof, it can be put into water, but it will be corrosion if long time stay the water
3. External Humidity sensor, not waterproof, it cannot put into water, cannot put in too wet environment.
4. The Internal sensor will slowly display than External sensor, because the internal sensor haven't enough air as test.
5. This thermometer isn't a toy products, need to be used under adult guidance.
6. All materials used ABS plastic, it is friendly for environment, Please recycle.

NO: 051-74